






LANTAO




1




2




3




4



1	1x
2	1x
3	1x
4	1x



1/1

A	M6X20	B	M6X12	C	M6X5	D	M6X35	E	Ø18xØ6x1.5	F	M4x25
	4x		4x		2x		2x		4x		4x
G		H	3MM 	I	4MM 						
	2x		1x		1x						

I.

1

F

M4x25

4x

G

2x

100%

2

D

M6x35

2x

H

3MM

1x

100%

3

C

M6x5

2x

H

3MM

1x

100%

II.

4

B

M6x12

4x

I

4MM

1x

75%

5

A

M6X20

4x

E

Ø18xØ6x1.5

4x

I

4MM

1x

75%

6

I

4MM

1x

100%



LE TRI
+ FACILE



Séparez les éléments avant de trier