










# Lindau




1	1X
2	1X
3	3X
4	1X
5	1X
6	1X
7	3X
8	1X



I.

1




- A M6x35  
6x  

- C Ø16XM6  
4x  

- D 4MM  
1x  

- 

2



- A M6x35  
6x  


- C Ø16XM6  
4x  

- D 4MM  
1x  

- 


II.


3



A	M4x30
	4x
D	4MM
	1x
	



4







A	M4x30
	4x
D	4MM
	1x
	



5



6



Séparez les éléments avant de trier