



AR4751K64904






QF5860




MADE IN ITALY
Produced by COMPOSAD srl, Via Lombardia 29, 46019 Viadana (MN) ITALY



2h



BU5046




M94
x1


BU5021




H325
x8



V57
x4



V45
x4



H337
x2




R40
x24




H129
x4



P39
x4



V81
x4



V5
x20



H54
x2




H2
x18




T134
x4




H113
x4




B23
x4




C66
x4




V5
x8







FI9385
1840x331x16mm



AN3227
1842x506x16mm




AN3229
1842x307x16mm




SH3818
1854x802x2mm


BOX 1/2




CA3932
823x352x30mm



BA2267
821x332x16mm






PI7602
787x315x16mm






BOX 2/2



1




2




3







Warning box containing a warning symbol, a crossed-out screw V45 (Ø10x50), and a correct screw V57 (Ø10x60).




4




5



















6




7


















12x







12x





12



13

